

Fig. 1




Fig. 2




Fig. 3




Figure 4




Fig. 5A




Fig. 5D




Fig. 5C




Fig. 5D




Fig. 6A




Fig. 6B




Fig. 6C




Fig. 6D




Fig. 7A




Fig. 7B




Fig. 7C

	<b>A</b>	<b>B</b>	<b>C</b>	<b>D</b>	<b>E</b>	<b>F</b>
<b>mw, cw</b>	5	3	5	5	5	3
<b>ml</b>	150	210	150	150	185	200
<b>cl</b>	100	90	100	100	80	90
<b>bl</b>	30	30	39	44	44	44
<b>conn_w</b>	25	15	42	45	13	13
<b>conn_l</b>	40	35	40	40	40	30
<b>Etch Holes</b>	None	None	15x30, t-hole	20x30, t-hole	20x30, no t-hole	20x30, no t-hole
<b>Twist</b>	<b>1.418</b>	<b>2.350</b>	<b>1.200</b>	<b>1.160</b>	<b>1.231</b>	<b>2.075</b>

Fig. 8




Fig. 9




Fig. 10